

CORPUS CHRISTI HOUSING AUTHORITY & AFFILIATES
RFQ 19017 - Patio Fence Replacement at Alaniz - Addendum #1

Date: August 15, 2019

Request for Quotations (RFQ) No. 19017 – Patio Fence Replacement at Alaniz, is hereby amended as follows:

(1) Question: Can you please clarify or send details as to what is a beveled sole plate?

Answer: A beveled sole plate is one that changes angle to be vertical with sloped angle of patio surface to keep upright.

All other terms and conditions of the Solicitation remains unchanged. **The signed addendum must be returned with your RFQ submission.**

Acknowledged and accepted:

Company: _____

Representative Name: _____

Signature: _____

Date: _____

